

Appl. No. 10/798,257

Amtd. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet




FIG.1.

BEST AVAILABLE COPY

Appl. No. 10/798,257

Amdt. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005


Replacement Sheet

FIG. 2.

BEST AVAILABLE COPY

Appl. No. 10/798,257

Amdt. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet

BEST AVAILABLE COPY




FIG. 3.


Appl. No. 10/798,257

Amdt. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet

FIG. 3b.





BEST AVAILABLE COPY

FIG.4.

Replacement Sheet

BEST AVAILABLE COPY



Appl. No. 10/798,257

Amdt. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet

Model  
Source  
Signal  
Input  
Output

Ser. No.  
Date

## 3 - Phase 3 - Wire




FIG. 5.

BEST AVAILABLE COPY

MAR-30-2006 11:56

DENNISON AND ASSOCIATES

416 368 1645

P.18

Appl. No. 10/798,257

Amtd. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet




FIG.16b.

BEST AVAILABLE COPY

Amdt. Dated March 30, 2006

Reply to Office action of Sept. 30, 2005

Replacement Sheet




FIG. 21.

BEST AVAILABLE COPY